

Figure 4 - Roughness, 2005 Conditions




Figure 5 - 2005 Existing Conditions, 100 Year ARI Maximum Water Surface Elevation




Figure 6 - 2005 Existing Conditions, 100 Year ARI Maximum Water Depth




Figure 7 - Topographical Features Within the Mooroopna ODP




Figure 8 - 2005 Mooroopna ODP, 100 Year ARI Maximum Water Surface Elevation




Figure 9 - 2005 Mooroopna ODP, 100 Year ARI Maximum Water Depth




Figure 10 - WSE Difference - ODP Minus 2005 Conditions, 100 Year ARI Event

Flooding Behaviour - Mooroopna ODP

**Report Prepared For
City of Greater Shepparton**

**Report LJ5470 / RM2125
April, 2007**

**Cardno Lawson Treloar Pty Ltd
Ground Floor
169 Burwood Road
Hawthorn VIC 3122
Australia**

**Telephone: 61 3 9818 3910
Facsimile: 61 3 9818 7033
Email: cltvic@cardno.com.au**

**A.B.N. 55 001 882 873
A.C.N. 001 882 873**



**CERTIFIED QUALITY
MANAGEMENT SYSTEM**

— ISO 9001 —